




SAVING MONEY

CHALLENGE

A meat processing plant was struggling to meet production deadlines due to the amount of time required to washdown all of their conveyor pulleys. Using traditional sprockets on square bar requires the pulleys be disassembled and all collars removed and sanitized. Additional concerns for the customer involved potential sprocket breakage and product contamination issues.

SOLUTION

It was determined a PPI Sanitary Pulley would be the best replacement option because the PPI Sanitary Pulley had the same price as the problematic product the client was using previously and did not require any disassembly for sanitation. Another benefit of a one-piece PPI Sanitary Pulley is no migration once installed so there are no concerns with sprocket breakage contaminating the product.



IMPACT

The customer had five conveyors running at \$20.00/hour maintenance they were saving \$100.00 per washdown.

COST SAVINGS

Washing down the equipment six times a week means the customer saved \$31,000.00 per year!



Call. 800-526-9328
Click. MotionIndustries.com
Visit. Over 550 Locations
f @ in + YouTube



Please contact your Motion Industries Representative for quotation.

Product shown are for illustrative purposes only and may display optional accessories or components. Please contact your sales representative for more information on product specifications. PPI respectively reserves the right to make changes in engineering, design and specifications; add improvements; or discontinue manufacturing at any time without notice obligation. Herringbone Wing, PPI and their respective logos are trademarks of Precision, Inc. in the US and or other countries.